
AR68.10-P-1030GH	Remove/install center section of instrument panel	11.4.97

MODEL 163

Illustrated on Model 163 up to VIN A289564, X754619

1 Instrument panel
2 Instrument panel center section
3 Stowage compartment
4 In-car temperature sensor intake hose
5 Long wedge
A2 Radio
Arrows Retaining clips




P68.10-2358-06

	Remove/install		
1	Remove radio (A2)		AR82.60-P-7502EA
2.1	Remove stowage compartment (3)	Only if present	
3	Pry off top retaining clips (arrows) at	Risk of cracks and fracture!	

© 2006 Mercedes-Benz USA, LLC

	center section of instrument panel (2) out of instrument panel (1)	Put long wedge (5) behind center section of instrument panel (2) on the top edges of the opening and carefully pry off top retaining clips (arrows).	
		Long wedge	115 589 03 59 00
4	Insert long wedge (5) into gap between instrument panel center section (2) and instrument panel (1) and pull down to rotary switches	Long wedge	115 589 03 59 00
5	Carefully pry off bottom retaining clips (arrows) at center section of instrument panel (2) out of instrument panel (1)	Risk of cracks and fracture!	
		Long wedge	115 589 03 59 00
6.1	Pull off interior temperature sensor intake hose (4)	Up to VIN A289564, X754619.	
7	Unplug all connectors from center section of instrument panel (2).		
8.1	Separate connectors from AAC pushbutton control module	As of VIN A289565, X754620.	
9	Remove instrument panel center section (2)		
10	Install in the reverse order		



115 589 03 59 00

© 2006 Mercedes-Benz USA, LLC

Long wedge

© 2006 Mercedes-Benz USA, LLC