

VIN	Model	164
	series/model designation	
Order number	License plate	

Full list of fault codes and events

9000	Control unit DCM-FL is defective.
9001	The parameterization of the power window is faulty.
9004	The left front power window relay is defective (the contact sticks in the switched state or the relay fails to energize).
9006	Components M21/1m1 (Mirror adjustment up/down motor) and M21/1m2 (Mirror adjustment in/out motor) are defective or the feed lines have Short circuit.
9007	Component M14/6 (Left front door central locking motor) or lead has Short circuit to ground.
9008	Component M21/1r1 (Mirror heater) or lead has Short circuit to ground.
9009	Component M21/1e1 (Left outside mirror ambient lamp) or lead has Short circuit to ground.
900A	Component M21/1e1 (Left outside mirror ambient lamp) or lead has Open circuit.
900C	Component E6/5 (Left exterior mirror turn signal lamp) or lead has Short circuit to ground.
900D	Component E6/5 (Left exterior mirror turn signal lamp) or lead has Open circuit.
900E	Component E17/3 (Left front door entry/exit lamp) or lead has Short circuit to ground.
900F	Component E17/3 (Left front door entry/exit lamp) or lead has Open circuit.
9014	S85/5 (Left interior CL [ZV] switch) : The component remains in the switched status (contact sticking) or has Short circuit to ground.
901A	Switching bus : At least one of the power window switches is stuck in the switched state (contacts stuck).
901B	Switching bus : At least one of the mirror adjustment switches is stuck in the switched state (contacts stuck).
901D	The switch lighting (terminal 58d) has a short circuit.
Event 9002	The supply voltage of control unit DCM-FL is too low (undervoltage).
Event 9003	The supply voltage of control unit DCM-FL is too high (overvoltage).

Tuesday, June 20, 2017 03:59:57

Page 1/2

12/2016 (2016-10-06)\AddOns: ([6988] (7160) (7258) (6755) (6933) (7418) (7176) (6765) (7292) (6726) (6832) (7030) (6815) (6961) (6892) (6927) (6642) (6882) (6977) (6604) (7100) (7128) (6819) (7134) (7069) (6785) (7229) (6669) (6658) (7309) (7188) (6728) (6569) (6843) (6826) (6818) (6997) (6896) (7172) (7092) (6931) (7084) (6951) (6835) (6691) (7014) (6622) (6792) (6828) (6768) (6985) (6721) (6745) (7154) (6677) (7143) (6817) (6919) (6780) (6707) (6686) (6863) (7002) (6991) (6700) (6615) (6803) (6880) (6580) (6646) (6576) (6986) (6814) (6670) (7009) (7018) (6781) (6673) (6877) (6864) (6872) (7033) (7256) (7318) (6730) (7104) (6663) (7147) (6798) (6994) (6858) (6898) (6871) (7386) (6704) (7029) (6822) (6850) (6796) (7065) (6802) (6971) (6874) (7072) (7082) (6746) (7239) (6772) (6857) (6949) (7180) (6831) (7086) (6627) (6916) (7206) (6742) (7042) (6964) (6870) (7166) (7138) (7080) (7398) (6848) (6975) (7001) (6760) (6679) (6845) (6732) (6565) (6941) (6902) (6890) (6847) (6842) (6856) (7359) (6578) (7007) (7185) (7158) (7026) (6894) (6980) (6739) (7119) (6684) (6995) (6816) (6809) (6784) (6972) (6633) (6952) (6648) (6943) (6793) (6981) (7135) (7036) (6608) (6907) (7023) (6861) (7113) (7433) (7209) (7324) (6954) (7097) (6705) (6825) (6968) (6885) (6616) (6573) (6759) (6676) (6682) (6887) (6910) (7226) (6914) (6866) (7360) (6886) (7233) (7108) (6953) (5226) (7267) (7121) (7201) (7063) (6599) (7049) (7216) (6649) (7055) (6774) (6724) (7225) (6990) (6833) (6965) (6906) (6800) (7251) (6962) (6958) (7068) (7071) (6900) (7316) (7289) (6788) (6851) (6709) (6948) (6983) (6769) (6714) (7190) (6924) (6889) (6921) (6911) (7012) (7150) (5225) (7164) (7198) (6588) (6903) (6697) (6596) (6839) (7058) (6790) (7109) (6787) (7052) (6868) (7300) (6653) (7248) (6884) (7032) (6735) (7046) (6876) (6630) (6806) (6904) (6659) (7458) (6867) (7008) (6946) (7184) (6879) (6841) (6912) (6570) (7142) (7077) (6801) (6618) (6976) (7313))

Event 9015 No signal from component 'S20/1 (Power window and outside mirror adjustment switch group, driver)' on switching bus.

Event 9019 The parameter set does not match model series.

Filename: C:\Program
Files\Mercedes-Benz\DAS\bin\..\trees\PKW\tuersg\tsgvl8\menues\mntsgvl1.s

Cell co-ordinate: 19 , 15