

Display Document

Sales designation:

Vehicle ident. number:

Engine number:

Automatic transmission:

Gr.:

Entry: Mod.Y.: Op. no.:

CLK 500

WDB209375*

113.968

722633

83.40

GF83.40-P-2182Q

Actuator motors for automatic air conditioning, location/task/function

Full-size view


Validity OFF

Page:

2 / 2

MODEL 209.3 /4 with CODE (581a) Air conditioning (Automatic)

- M2/5 Fresh air/recirculated air flaps actuator motor
- M2/6 left blending air flap actuator motor
- M2/7 Right blended air flap positioning motor
- M2/15 Left and right footwell flaps positioning motor
- M2/16 Left and right defroster flaps positioning motor
- M2/21 Fresh air flaps positioning motor



P83.40-2192-06

Add.

Document

What is

Document:

Level:

Menu

Help

Previous

Screen

Display Document

Sales designation:	Vehicle ident. number:	Engine number:	Automatic transmission:	Gr.:	Entry:	Mod.Y.:	Op. no.:
CLK 500	WDB209375*	113.968	722633	83.40			

GF83.40-P-2183Q

Actuator motors for comfort automatic air conditioning, location/task/func

Full-size view


Validity OFF

Page:

2 / 2

MODEL 209.3 /4 with CODE (581b) Convenience automatic air conditioning

- A32m2 Activated charcoal filter flap adjustment motor
- M2/5 Fresh air/recirculated air flaps actuator motor
- M2/6 Left blended air flap positioning motor
- M2/7 Right blended air flap positioning motor
- M2/8 Left defroster vent flap actuator motor
- M2/9 Right defroster vent flap actuator motor
- M2/10 Left footwell flap positioning motor
- M2/11 Right footwell flap positioning motor
- M2/19 Left fresh air flap positioning motor
- M2/20 Right air vent flap positioning motor



P83.40-2189-06

Add.

Document

What is

Document:

Level:

Menu

Help

Previous

Screen