



P82.35-2454-08

Vehicles without Active Body Control (ABC), code 487

- 1 Cover
- 2 Reservoir

Vehicles with Active Body Control (ABC), code 487

- 1 Cover
- 2 Reservoir

	Checking		
Danger!	Risk of fire and explosion caused by igniting windshield cleaning agent and antifreeze and their vapors. Risk of poisoning caused by swallowing windshield cleaning agent and antifreeze and inhaling their vapors. Risk of injury caused by irritation in the event of contact of windshield cleaning agents and antifreezes with eyes, mucous membrane and skin	Wear protective clothing and tight-fitting safety glasses. Keep away from open flames, fire and ignition sources. Avoid contact with eyes, mucous membrane and skin. Do not eat, drink or smoke when dealing with windshield cleaning agents and antifreezes. Do not inhale vapors, ensure adequate ventilation. Only store windshield cleaning agents and antifreezes in tightly sealed original containers and which are inaccessible to children.	AS82.35-Z-0001-01A
1	Open engine hood and raise to vertical position		
2	Open hood (1) and fill reservoir (2) of windshield washer system with windshield washer fluid	Pay attention to mixing ratio according to table on the packaging of the windshield washer fluid concentrate. Windshield washer fluid Sheet 371.0	*BF82.35-P-1001-01F BB00.40-P-0371-00A
BB	Windshield washer fluid concentrate		
3	Seal reservoir (2) of windshield washer system with cap (1)		
4	Close engine hood		

Windshield washer system filling capacity

Number	Designation	Model 216	Model 221
BF82.35-P-1001-01F	Windshield washer fluid		
	Filling capacity Liters	6,4	6,4