






TorqueConverter

Gear Box






Retainer / Oring

Busing

Busing is loose , it can freely rotate. I think leak is coming from here.





Retainer & Busing





